

<meta http-equiv="Content-Type" content="text/html; charset=us-ascii"><title>EEC Work Log Update - Staff</title><br><span><strong style="color:#288054;">Auto Email: Work Log Updated</strong></span><br><hr><span><strong style="color:#00485b;">ID: </strong>6025    <a href="LINK GOES HERE/ccs\_EditForm.aspx?ID=6025" target="\_blank" title="Click to Edit or Update this Work Order"><strong>Edit Work Order</strong></a><br><strong style="color:#00485b;">Title: </strong>Remove pipe and plug floor<br><strong style="color:#00485b;">Requester: </strong>Matter, Craig<br><strong style="color:#00485b;">Category: </strong>General<br><strong style="color:#00485b;">Issue Type: </strong>Demolition<br><strong style="color:#00485b;">Source: </strong>Requester<br><strong style="color:#00485b;"> Area: </strong>West Process - 2nd North<br><strong style="color:#00485b;">Due Date: </strong>5/28/2021<br><strong style="color:#00485b;"> Priority: </strong>Normal<br><strong style="color:#00485b;">Assigned Staff: </strong>Patton, Joseph<br><strong style="color:#00485b;">Assigned Team: </strong><br><strong style="color:#00485b;">Description: </strong><div class="ExternalClass048B5E9493964D4982C15D83490C635

E">I believe we use to have steam lines run down through this pipe. Any reason why we can't remove pipe and weld floor level</div><br></span><br><span><strong style="color:#288054;">Work Log:  
</strong><br><table style="border-spacing:0;"><tbody><tr style="background-color:#ffffff;padding:4px;"><td style="padding:4px;vertical-align:top;"><strong>Patton,, Joseph</strong> (04/28/2021 04:41 PM):</td><td style="padding:4px;max-width:500px;"><div class="ExternalClass87842436E5984835938DAA2FA2308C2D">pipe has been cut down and capped with fire proof puddy for future use.&nbsp;  </div></td></tr></tbody></table></span><br>